

Oil Field Environmental Incident Summary

Incident: 20150418131542 **Date/Time of Notice:** 04/18/2015 13:15

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: BRODERSON 31X-27G

Field Name: SIVERSTON

Well File #: 26454

Date Incident: 4/16/2015 **Time Incident:** 18:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 98

Sec: 27

Qtr:

Location Description:

Submitted By: JORDAN WOLF

Received By:

Contact Person: KAYLAN DIRKX
2320 SOUTH CENTRAL AVE
SIDNEY, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	60	Barrels	1	Barrels	1	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/24/2016

Clean Up Concluded: 4/20/2015

Risk Evaluation:

None- spill was contained on well site.

Areal Extent:

Potential Environmental Impacts:

None- spill was contained on well site.

Action Taken or Planned:

All drivers are required to be out of their truck to witness the fluid transfer.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 4/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.